

VIN REPORT

5N1AT2MT7KC773413 ↗

NISSAN ROGUE

2019 2019 NISSAN ROGUE S/SL/SV

FIRST SEEN	LAST SEEN	DAYS TRACKED
—	—	—

- 1 listing
- 1 damage event
- Source · IAAI
- Lot #39488902



ODOMETER —	BODY SPORT UTILITY VEHICL	TRANSMISSION —	DRIVETRAIN FRONT WHEEL DRIVE	PRIMARY DAMAGE Left front	CONDITION Listed (auction)
---------------	-------------------------------------	-------------------	--	-------------------------------------	--------------------------------------

Sale price across listings USD · 0 data points

Not enough auction data yet.

All listings · 1

DATE	SOURCE	LOT ID	DAMAGE	STATUS	PRICE	LINK
—	IAAI	#39488902	Left front	—	—	Open →

Specs

VIN · 5N1AT2MT7KC773413

Year	2019	Make	NISSAN
Model	ROGUE	Body	SPORT UTILITY VEHICL
Engine	2.5L I4 FI DOHC 16V NF4	Transmission	—
Drivetrain	FRONT WHEEL DRIVE	Fuel	Unknown
Cylinders	—	Odometer	—
Color	● Red	Title	2019 NISSAN ROGUE S/SL/SV
Location	McAllen (TX)	Primary damage	Left front
Secondary		VIN status	Unknown

Vehicle history

1 event · first seen —

LISTINGS 1	FIRST SEEN —	LAST SOLD PRICE —
—	<input checked="" type="radio"/> Listed IAAI · McAllen (TX)	—