

VIN REPORT

# 5N1AT2MV7HC819137 ↗

NISSAN ROGUE SV

2017 2017 NISSAN ROGUE SV

• 1 listing

1 damage event

Source · Copart

Lot #57259924

FIRST SEEN  
Jul 2024

LAST SEEN  
Jul 2024

DAYS TRACKED  
672



ODOMETER 107,141 mi	BODY —	TRANSMISSION Automatic	DRIVETRAIN ALL WHEEL DRIVE	PRIMARY DAMAGE Rear end	CONDITION Listed (auction)
------------------------	-----------	---------------------------	-------------------------------	----------------------------	-------------------------------

**Sale price across listings** USD · 0 data points

Not enough auction data yet.

**All listings · 1**

DATE	SOURCE	LOT ID	DAMAGE	STATUS	PRICE	LINK
Jul 15, 2024	<a href="#">COPART</a>	#57259924	Rear end	<a href="#">F</a>	—	Open →

### Specs

VIN · 5N1AT2MV7HC819137

Year	2017	Make	NISSAN
Model	ROGUE SV	Body	—
Engine	2.5L 4	Transmission	Automatic
Drivetrain	ALL WHEEL DRIVE	Fuel	Gas
Cylinders	4	Odometer	107,141 mi
Color	● White	Title	2017 NISSAN ROGUE SV
Location	PA - YORK HAVEN	Primary damage	Rear end
Secondary	Side	VIN status	Unknown

### Vehicle history

1 event · first seen Jul 2024

LISTINGS

1

FIRST SEEN

Jul 2024

LAST SOLD PRICE

—

Jul 15, 2024 ● F  
Copart · PA - YORK HAVEN