

VIN REPORT

JTHBF5C22B5137611 ↗

LEXUS IS 250

2011 2011 LEXUS IS 250

FIRST SEEN	LAST SEEN	DAYS TRACKED
—	—	—

- 1 listing
- 1 damage event
- Source · IAAI
- Lot #39202833



ODOMETER	BODY	TRANSMISSION	DRIVETRAIN	PRIMARY DAMAGE	CONDITION
187,511 mi	—	Automatic	REAR WHEEL DRIVE	Front end	Listed (auction)

Sale price across listings USD · 0 data points

Not enough auction data yet.

All listings · 1

DATE	SOURCE	LOT ID	DAMAGE	STATUS	PRICE	LINK
—	IAAI	#39202833	Front end	—	—	Open →

Specs

VIN · JTHBF5C22B5137611

Year	2011	Make	LEXUS
Model	IS 250	Body	—
Engine	2.5L V-6 DI, DOHC, VVT, 204HP	Transmission	Automatic
Drivetrain	REAR WHEEL DRIVE	Fuel	Gasoline
Cylinders	6	Odometer	187,511 mi
Color	● White	Title	2011 LEXUS IS 250
Location	Little Rock (AR)	Primary damage	Front end
Secondary		VIN status	Unknown

Vehicle history

1 event · first seen —

LISTINGS

1

FIRST SEEN

—

LAST SOLD PRICE

—

- **Listed** —
IAAI · Little Rock (AR)